

KERO-KLEAN™

KERO-KLEAN™ prevents the tar/carbon residue from accumulating at the top of the wick, causing unpleasant odor, smoke and soot.

DIRECTIONS

Add ½ oz. additive to a five-gallon can before filling with kerosene. Use up to 2 oz. if needed.

KEEP OUT OF REACH OF CHILDREN

Flammable – Vapor Harmful

Fatal or causes blindness if swallowed. Read caution carefully.

CAUTION

Contains methyl alcohol. Cannot be made non-poisonous. Use only in well ventilated areas. Keep away from heat and open flames.

FIRST AID IF SWALLOWED: Give 1 or 2 glasses of water. Call physician, hospital emergency room or poison control center immediately for instructions to induce vomiting. When medical advice is not available, induce vomiting by using syrup of Ipecac according to directions. If Ipecac is unavailable, induce vomiting with finger or back of spoon. Get prompt medical attention.

Manufactured exclusively for:
World Marketing of America, Inc.
PO Box 192
Mill Creek, PA 17060

Part No: PW-11

© 1992 All Rights Reserved. World Marketing of America, Inc.