

## Kozy World 2015 Dual Fuel Gas Wall Heaters/Log Sets

**Issue:** In some on natural gas installations the LP pilot may have a flickering or fluttering sound.

**Solution:** Due to the design of the ODS safety system, the LP pilot may have some gas flow when the heater is set to NAT gas. This will not be enough gas to support a continuous LP pilot but may create a flickering or fluttering sound. If needed an ODS pilot clip (see below image) that will reduce this noise is available from World Marketing of America. This clip takes only seconds to install and must completely cover the hole in the LP ODS. This clip must be removed if the heater is converted back to LP. Complete instructions that are included with the clip should be followed.

